

SC Stivuitoare-Lize SRL Telefon: 0040 744 136 717 Email: office@stivuitoare-lize.ro

Website: http://stivuitoare-lize.ro/

Comuna Corunca, Str. Principala, nr. 412-413, judet Mures, Romania

Intrerupator coloana directie stivuitor Valeo/032654





- SPECIFICATIONS -

Number of connections	2
Type of the connection	wire with connector
Number of wires	14
Number of pins	14
Diameter steering column mounting D1 (mm)	44.5
Total length of the steering column switch L1	258
(mm)	
Total width of the steering column switch W1	79
(mm)	
Total height of the steering column switch H1	120
(mm)	
Length of the cable L2 (mm)	1360
Number of mounting holes	2
Thread size TA1	M5
Pitch (metric) TA1 (mm)	0.8
Right or left handed thread	right-handed
Shortest center distance between mounting	65
holes C1 (mm)	
Material of the housing	plastic
Number of levers	1
Forwards present	NO
Neutral present	NO

Reverse present	NO
Neutral Lock present	N0
Park present	N0
Slow speed present	NO
Fast speed present	NO
Gear present	NO
Automatic gear selection present	NO
Cruise control present	N0
Horn present	YES
Left/right direction indicator present	YES
Position light present	NO
Low beam present	YES
High beam present	YES
High beam flashing present	YES
Master light switch present	NO
Automatic light present	NO
Fog light present	NO
Warning light present	NO
Worklight present	NO
Revolving/ strobe light present	NO
Wiper present	YES
Windscreen washer present	YES

Intrerupator coloana directie stivuitor Valeo/032654 Se emite factura Pret: 150€ fara TVA

- SPECIFICATIONS -

Number of connections	2
Type of the connection	wire with connector
Number of wires	14
Number of pins	14
Diameter steering column mounting D1 (mm)	44.5
Total length of the steering column switch L1	258
(mm)	
Total width of the steering column switch W1	79
(mm)	
Total height of the steering column switch H1	120
(mm)	
Length of the cable L2 (mm)	1360
Number of mounting holes	2
Thread size TA1	M5
Pitch (metric) TA1 (mm)	0.8
Right or left handed thread	right-handed
Shortest center distance between mounting	65
holes C1 (mm)	
Material of the housing	plastic
Number of levers	1
Forwards present	NO
Neutral present	NO

Reverse present	NO
Neutral Lock present	N0
Park present	N0
Slow speed present	N0
Fast speed present	NO
Gear present	N0
Automatic gear selection present	N0
Cruise control present	N0
Horn present	YES
Left/right direction indicator present	YES
Position light present	N0
Low beam present	YES
High beam present	YES
High beam flashing present	YES
Master light switch present	N0
Automatic light present	N0
Fog light present	N0
Warning light present	N0
Worklight present	NO
Revolving/ strobe light present	N0
Wiper present	YES
Windscreen washer present	YES







SC Stivuitoare-Lize SRL Telefon: 0040 744 136 717

Email: office@stivuitoare-lize.ro

Website: http://stivuitoare-lize.ro/

Comuna Corunca, Str. Principala, nr. 412-413, judet Mures, Romania